




VERIFICATION OF COMPLIANCE

This Verification of Compliance is hereby issued to the product designated below.

Product	Shaft motor
Model	RMT1306D05; RMS1306D33; RMS1306D05; RMT1306D33
Trade name	RISUN
Applicant	RISUN EXPANSE CORP. 1F, No. 22, Lane 24, Sec. 1, Hwan-Shan Rd., Taipei, Taiwan, R.O.C.
Applicable Standard(s)	EN 55022: 1998 + A1: 2000 + A2: 2003 EN 55024: 1998 + A1: 2001 + A2: 2003 IEC 61000-4-2: 1995 + A1: 1998 + A2: 2000; IEC 61000-4-3: 2002 + A1: 2002; IEC 61000-4-4: 1995 + A1: 2000; IEC 61000-4-6: 1996 + + A1: 2000; IEC 61000-4-8: 1993 + A1: 2000
Report No.	61130101-E
Test Laboratory	Compliance Certification Services Inc. No. 81-1, Lane 210, Bade Rd., 2, Luchu Hsiang, Taoyuan Hsien, Taiwan, R.O.C. Tel: +886-3-3240332/ Fax: +886-3-3245235

This device has been tested and found to comply with the stated standard(s), which is(are) required by the Council Directive of 89/336/EEC and Amendment Directive of 93/68/EEC. The test results are indicated in the test report and are applicable only to the tested sample identified in the report.



Miller Lee / Deputy Manager of Linkou Laboratory
Date: December 7, 2006

